


CENTRAL FILE COPY

T/N-17

Master



TECHNICAL NOTE

Filing Code 1525 (P-401)

Date Issued October 1969

Bureau of Land Management U.S. DEPARTMENT OF THE INTERIOR

CHEVROLET STAKE TRUCK TIRE CHAIN CLEARANCE

The 1969 Chevrolets, Model C-30, with dual rear wheels do not have adequate clearance for installation of dual wheel tire chains (Classes 195, 196, 197, 198, and 199). Due to the clearance of less than 1.3 in. between the inside tire and spring, it will only be possible to install single tire chains on each outer dual wheel and tire.